From: Trowbridge, Philip

Sent: Fri, 5 Jul 2024 16:09:27 +0000

To: Blecharczyk, Jeffrey; Schlosser, Michael

Subject: FW: DES and NH AG

Attachments: wetlands violations eversource.pdf, X-178 AoT application apparent

inaccuracies 5-2024.pdf, insufficiencies in x-178 AoT.pdf

Philip Trowbridge, P.E., Manager Land Resources Management Program Water Division, NH Department of Environmental Services P.O. Box 95 Concord, NH 03302-0095 phone (603) 271-4898

We greatly appreciate your feedback. Please take a moment to fill out our 3-minute <u>NHDES-LRM customer satisfaction survey</u>.

From: Scott, Robert < Robert.R.Scott@des.nh.gov>

Sent: Friday, July 5, 2024 9:59 AM

email: Philip.R.Trowbridge@des.nh.gov

To: Trowbridge, Philip < Philip.R. Trowbridge@des.nh.gov>

Subject: Fwd: DES and NH AG

Robert R Scott

Commissioner

New Hampshire Department of Environmental Services 29 Hazen Drive, PO Box 95 Concord, NH 03302-0095

W: 603.271.2958 C: 603.892.1706

robert.r.scott@des.nh.gov

From: Kris pastoriza INV OF PRIVACY

Sent: Friday, July 5, 2024 3:56:50 AM

To: DES: Wetlands Application Public Comments < wetlandsapplicationpubliccomments@des.nh.gov>; Aslin, Christopher < Christopher.Aslin@doj.nh.gov>; Scott, Robert < Robert.R.Scott@des.nh.gov>

Cc: Nelson, Kurt I < kurt.nelson@eversource.com>; Robert Blechl < rblechl@caledonian-record.com>; bosrice@woodstocknh.gov < bosrice@woodstocknh.gov>; dalybos@lincolnnh.org < dalybos@lincolnnh.org>; hambos@lincolnnh.org < hambos@lincolnnh.org>; bosrand@woodstocknh.gov < bosrand@woodstocknh.gov>; Town Admin < townadmin@townofdaltonnh.gov>; Oberlin, Brent < bosreardon@iso-ne.com>; Whitefield Planning Board < whitefieldtax@ne.rr.com>; bosreardon@woodstocknh.gov < bosreardon@woodstocknh.gov>; Vivian Winterhoff < conservationcommission@bethlehemnh.org>; pacmatters@iso-ne.com < pacmatters@iso-ne.com>; selectman5@bethlehemnh.org>; Easton Planning Board < eastonnhplanningboard@gmail.com>; Easton SelectBoard < eastonnhselectboard@gmail.com>; Linda Hansen < eastonconservationcommission@gmail.com>; Sugar Hill Selectmen < selectmen@sugarhillnh.org>; Nancy West < nancywestnews@gmail.com> Subject: DES and NH AG

EXTERNAL: Do not open attachments or click on links unless you recognize and trust the sender.

DES and the New Hampshire Attorney General have allowed Eversource to sign the AoT permits for its 70+ transmission line rebuilds as "owner" or agent of the land on which it has easements.

DES, the New Hampshire Attorney General and Eversource willfully excluded transmission easement-encumbered landowners from the AoT permitting process, in violation of DES's own rules.

| Initials: KN | If the applicant is not the owner of the property, each property owner signature shall constitute certification the signer that he or she is aware of the application being filed and does not object to the filing. | | | |
|---|--|---|------------------------------------|--|
| SECTION 1 | 5 - REQUIRED SIGNATURES (Env-Wt 311 | .04(d); Env-Wt 311.11) | | |
| SIGNATURE (OWNER): | | PRINT NAME LEGIBLY: Kurt Ne | DATE: 2/21/20 | |
| SIGNATURE | NATURE (APPLICANT, IF DIFFERENT FROM OWNER): PRINT NAME LEGIBLY: | | DATE: | |
| SIGNATURE (AGENT, IF APPLICABLE): Links White | | PRINT NAME LEGIBLY: Lindsey | White DATE: 2/21/20 | |
| SECTION : | 16 - TOWN / CITY CLERK SIGNATURE (Em | r-Wt 311.04(f)) | | |
| As require | ed by RSA 482-A:3, I(a)(1), I hereby certify I four USGS location maps with the town, | that the applicant has filed for city indicated below. | ur application forms, four detaile | |
| TOWN/CITY CLERK SIGNATURE: | | PRINT NA | PRINT NAME LEGIBLY; | |
| TOWN/CITY: | | DATE: | DATE: | |

"If the applicant is not the owner of the property, each property owner signature shall constitute certification by the signer that he or she is aware of the application being filed and does not object to the filing."

DES, the New Hampshire Attorney General and Eversource failed to inform easementencumbered landowners of this act, for obvious reasons.

DES, the New Hampshire Attorney General and Eversource need to remedy these violations, repeated over the past seven years in 70+ Eversource transmission projects, and inform the public and the thousands of New Hampshire transmission easement-encumbered landowners about these violations. This announcement needs to appear in local newspapers and be sent to all towns and transmission-encumbered landowers. Damages are due to easement-encumbered landowners, who were neutered in a permitting process which is already skewed in favor of corporate applicants; a rubber stamp permit.

Eversource claims the AoT application files are too large to send to the few individuals and towns that have requested them!

DES and Eversource need to provide links (that work) for all Eversource AoT applications and place the X-178, U-199, Q-195 and S-136 permitting on hold until these applications are available on the Eversource project sites, functional on the DES site, and hard copies have been sent to all easement-encumbered landowners.


DES is responsible for the lack of inspections and enforcements and the violations of the conditions of its AoT permits to Eversource.

Towns in which Eversource transmission lines are rebuilt need to require Eversource to pay for third party inspection services, chosen by the town.

kris pastoriza easton, nh

Documentation of Eversource "Asset Condition" projects failure to use Best Management Practices as defined in 'Best Management Practices Manual, Utility Maintenance in and Adjacent to Wetlands and Waterbodies in New Hampshire.'

https://www.nh.gov/nhdfl/documents/new_final_utility_bmp_manual_3_8_19.pdf



(Above: 391/373, 1/2/2024) All photos are of Eversource "Asset Condition projects.

"2.6 Operating Adjacent to Wetlands and Waterbodies

Work adjacent to wetlands and waterbodies, but not necessarily in wetlands and waterbodies, can present potential environmental impacts. Care must be taken when working in these areas in order to protect these existing resource buffers. To minimize erosion potential, preserve low-growing vegetation adjacent to wetlands or waterbodies to the fullest extent possible.

Stumps and rocks must not be removed unless required for safety reasons..."




(Above and below: 391/373 1/2/2024)





"Install temporary erosion controls immediately prior to initial disturbance of the soil. Temporary erosion controls must be properly maintained throughout construction, on a daily basis and reinstalled as necessary until replaced by permanent erosion controls or restoration is complete." (Above and below: 391/373 1/2/2024)



"18 2.11.2 Upland Restoration

If exposed soils present sedimentation issues to adjacent wetlands and waterbodies, provide permanent soil protection. On steep slopes, install erosion control blankets as needed. " (*Below: 391/373 1/2/2024*), *2/18/2024*)





Best Management Practice 3: Temporary Construction Exit





(Above: 391/373 1/2/2024)

(Below: 391/373 1/2/24)



(Below: U-181 U-194)



"Description

A temporary stabilized construction exit consists of a pad of stone aggregate placed on a geotextile filter fabric, located at any point where traffic will be leaving a construction site to an existing access road way or other paved surface. Its purpose is to reduce or eliminate the tracking of sediment onto public roads by construction vehicles. This helps protect receiving waters from sediment carried by stormwater runoff from public roads.

Only construction traffic leaving the site is required to use the temporary stabilized exit.

Consider providing a separate, unprotected entrance for traffic entering the site. This will increase the longevity of the stabilized exit by reducing heavy loads and the total traffic over the device.

Locate construction entrances and exits to limit sediment leaving the site and to provide for maximum utility by all construction vehicles. Avoid exits that have steep grades or that are located at curves in public roads.

Installation

Temporary stabilized construction exits should meet the following requirements:


The minimum size stone used should be three-inch crushed stone.

The minimum length of the pad should be 75 feet, except that the minimum length may be reduced to 50 feet if a three- to six-inch high berm is installed at the exit of the project site.

The minimum depth of the pad should be at least six inches thick.

The pad should slope away from the existing roadway.

Natural drainage that crosses the location of the stone pad should be intercepted and piped beneath the pad, as necessary, with suitable outlet protection"



(Below: U-181 E-194, 2/23/2024)





(Above: 2/3/2024 373/391)



Mt. Rd. southerly





Left:
Brown
Rd.
Westerly
Right:
Rt. 107
northerly





Left: Brown Rd. westerly



Best Management Practice 4: Coir Logs



"Considerations

Consider using coir logs where slopes are susceptible to sheet and rill erosion, to freeze and thaw activity, or where slopes are difficult to vegetate because of soil movement.

Coir logs can be staked with live stakes, if site conditions warrant. The moisture retained by the coir log will encourage cutting establishment.

Installation

For slope stabilization, it is critical that coir logs are installed perpendicular to soil movement and parallel to the slop contour.

Coir logs, especially if used in slope stabilization, are not effective unless entrenched. Construct trenches half the diameter of the log in which to place the roll. Install rolls from the bottom of the slope and work up.

Lay the coir log along the trench, snugly fitting it against the soil. Ensure no gaps exist between the soil and the fiber roll.

Install stakes at least every three feet apart along the length of the roll. Additional stakes may be driven on the downslope side of the trenches on highly erosive or very steep slopes Consider using coir logs where slopes are susceptible to sheet and rill erosion, to freeze and thaw activity, or where slopes are difficult to vegetate because of soil movement."



(Above: 1/2/24 391/373, Below: E-194/U-181, 2/25/2024)







(Above and below: 1/2/24 391/373)



Best Management Practice 5: Silt Fence



No photos of silt fence available. Below: 373 and 319 easement, silt, no silt barrier



Below: A-111 easement. Silt, no fence.



"Do not install straw or hay bale barriers across streams, channels, swales, ditches or other drainage ways, or areas with concentrated flows. Such barriers are not capable of effectively filtering the high rates and volumes of water associated with channelized flow. However, they may be used for check dams in applications where



installation access or other conditions prevent the use of preferred materials such as stone. In such cases, embed the straw or hay bales within the concentrated flow path; otherwise, they are subject to undercutting and end cutting. This frequently not only results in the bypass of sediment laden-water, but also in the complete failure of the barrier. Such failures typically release sediment accumulation on the upgradient side of the barrier and severe erosion of the channel both upstream and downstream of the device. Under no circumstances should sediment barriers be constructed in live streams or in swales where there is a possibility of a washout."



(Above: 1/2/24, 2/18/2024; 391/373) Straw bales installed in swale, not "embedded within the concentrated flow path". No erosion matting.

Wetlands and Waterbodies in New Hampshire





(Right: 391/373: 2/12/2024) No coir no silt barriers, mats uncleaned and extended in width by improper placement of lower matting/support.





Constructing a swamp mat bridge span reduces direct impacts to the wetland surface and maintains aquatic organism passage through the construction area. The number of necessary swamp mats may be reduced using this method.

Below: U-181/E-194 12/2/2023) Wetlands impacts extended by lower layer.

"Description
Swamp mats may
be used as a
temporary bridge
over a stream to
allow vehicles
access to the work
site. Small sections
of mat are placed
within and along
the stream, parallel
to the flow of
water. These act as
supports. Mats may
then be placed



perpendicular to the stream, resting on top of the initial swamp mat supports. It may be necessary to place a large steel plate along the top of the swamp mats for extra stability and to minimize the amount of sediment that could fall between the spaces of each timber.



(Right: U-181/E-194 12/2/2024) Silty gravel dump above wetland.



Below: 1/2/24, easement with lines 373 and 391, wetland with no matting, coir coils, hay bales, protection of any kind. The equipment used to construct this area was working for a month prior to the photos of the matting being placed.



"Considerations

Minimize impact to wetland areas during installation, use and removal.

Swamp mats should be removed as soon as possible following completion of maintenance activities to reduce compaction of the underlying soil."

Comment: 2/16/2024: The great swamp access road is still is still under mats from the Greenland Rd crossing of the 345 and the (2)115's. It appears Eversource removed the pads at the structures but the entire road is intact through the swamp. The mats have been there for months with hundreds of trips across them.

Many pole butts are being left in the wetlands. The poles are cut with the stub left sticking up. It is easier than pulling it and backfilling it.

"If construction mats are used ensure they are free of invasives (particular consideration if using timber mats) before arriving on site and clean as with other equipment when moving. Properly treat or dispose of invasive species, or any materials that may harbor invasive species...

Avoid spreading seeds and other propagules from infested to non-infested areas during activities.

Considerations:

- a. Treat infestations before other activities begin in order to limit the spread of propagules.
- b. Carry out activities under conditions that minimize the risk of spread, e.g., frozen ground, snow cover, seed/propagule absence, etc. (See Figure 1)
- c. Clean equipment after activities in infested areas.
- d. Run equipment air intake fans in reverse before moving from infested to non- infested areas.
- e. Check non-infested areas for new invasions where activities have taken place 1-2 years after the activity."

https://dnr.wisconsin.gov/sites/default/files/topic/Invasives/bmp_WetlandInvasive.pdf

Below left U-181/E-194, 2/18/2024, partial mat removal in an area colonized by invasive phragmites. No proof that any of the above measures were carried out.





Best Management Practice 15: Erosion Control Blankets



(Below: 1/2/24, easement with lines 373 and 391)



(1/2/24, 373/391) No erosion control blankets, glacial erratic dump pile.





Below: 307/391, 2/12/2024



304.4

Crushed

0 - 5

2/28/2023: "The purpose of the site inspection was in response to concerns about construction practices" (DES)

'The siting of new poles is per engineer specifications and located approximately 10 feet off center from the existing poles. They use a pressure drill rig to pore new holes. Then insert a corrugated metal pipe (CMP) to be used as a sona tube for back filling once the pole is inserted. Depth can be up to 15 feet in the ground. Clean fill in the CMP meets NHDOT 304.04 sieve size and is compacted in lifts. The exterior of the CMP's in uplands is backfilled with either 8 inches of flowable fill or 10 inches of NHDOT 304.4. In wetlands they do not add any additional material

around the outside. Site was covered in snow, no active work taking place. All pole work had been completed, new poles were installed, and old poles had been removed. Preparing to close out the work site in coming months."

| Item | Stone (Fine) |
|-----------------------------|-----------------|
| Sieve Size | Percent Pass |
| 6" | 257024 |
| 5" | RALES |
| 4" | 3 |
| 3 1/2" | 10.000 |
| 3" | 18.555 |
| 2 1/2" | 1440 |
| 2" | 100 |
| 1 1/2" | 85 - 100 |
| 1" | See S |
| 3/4" | 45 – 75 |
| 1/2" | |
| #4 | 10 - 45 |
| # 200 (In Sand Portion)* | |

200 (In Total

Sample)

Item No.




* Fraction passing the # 4 sieve 2/12/2024 E-194

| | fill used on any of the Asset Condition projects to see if it meets | | | |
|--|---|--|--|--|
| standards or if it is high in silt? Does the black pole coating contain PFAs or other toxins? | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| kris pastoriza | march 2024 | | | |
| | | | | |

To Eversource and DES permitting,

please explain why the portion of the X-178 proposed project covered by this AoT application is stated to be "within a public right-of-way"?




"This worksheet is for residential utility projects and other utility projects within a public right-ofway."

Since the easement in this AoT is not within a public right-of-way, but on private properties, where is the proper form?


kris pastoriza easton, nh INV OF PRIVACY

(Eversource claims it is unable to provide Easton with a digital copy of the AoT application.)



To Eversource permitting,

I repeat my May 30 request: Explain why the portion of the X-178 proposed complete line rebuild covered by this AoT application, 'Easton non-WMNF,' is stated to be "within a public right-of-way."



"This worksheet is for residential utility projects and other utility projects within a public right-of-way."

Since it is not within a public right-of-way, but on private easements, where is the form that must be filled out?

#2. The application states "Due to updates to the National Electrical Safety Code Standards (NESC) since the X178-2 Transmission line was originally built in 1969 and additional portions were built in 1985, structure heights of new structures are required to be taller than existing wooden poles to meet new NESC clearances."

- The X-178 section covered in the AoT application was built in 1948 and replaced in 1985.
- The existing line is in conformance with Code, or at least, grandfathered.
- The distances of the existing conductors to ground, which would show inadequate clearance if it exists, are not given.
- Eversource's proposed clearances to ground for the high-sag 1272 ACSS conductor routinely exceed that required by code, by many feet.
- If the OPGW (not permitted in the easements) really needs to be 15' from the conductors, say that and show where in the Code book that is stated.
- **#3.** Where is the acceptance by DNCR that should follow their notification that the AoT application was incomplete?

| DHR Comment/Finding Recommendation This Space for Division of Historical Resources Use Only |
|--|
| ☐ Insufficient information to initiate review. ☐ Additional information is needed in order to complete review. |
| ☐ No Potential to cause Effects ☐ No Historic Properties Affected ☐ No Adverse Effect ☐ Adverse Effect |
| Comments: Project was already Subnitted for review M 9/1/33. On 9/15/33. Diff regues feet The results Diffe or were oligical survey of the grephs tin of an Green feeting Since plan. To dark Diffe has rearred the orchaeological right but a waiting or the architectures way plan before additional common can be made. If plans change or resources are discovered in the course of this project, you must contact the Division of |
| Historical Resources as required by federal law and regulation. |
| Authorized Signature: Jackil Mult, DSMP Date: 12/1/23 |

"DHR...is waiting on the architectural survey plan before additional comments can be made."

#4. The PROJECT NEED statement is simply not true.

- If a pole was unsafe it would be immediately replaced (or reinforced or restored???)
- "Reliability" is misleading (a euphemism), because it implies that ISO has designated the X-178 as a reliability project.

- Cross-arms and insulators that needed replacement were replaced around 2017 and there
 are only 41 poles needing replacement /reinforcement within 8-10 years and no poles
 that require immediate replacement.
- Eversource appears to be creating new criteria for structure ratings; any replacements of existing structures are now claimed to be "beneficial to public health and safety". The externalized costs of constructing new transmission lines are ignored.
- Will Eversource claim economic benefits of line rebuilds next, transposing the Kelo decision to its asset condition projects?
- "...the structures are old and worn..." Is this statement all DES requires as evidence?
- "...must be replaced due to the state of deterioration of these structures..." Again, simply not true.
- A "state of deterioration" is measured on a given day, so to write "the state of deterioration of these structures over the past 55 and 39 years" is poor writing.

PROJECT NEED

Eversource supplies electrical transmission and distribution services from within their existing, maintained ROWs. Maintenance of Eversource's electrical infrastructure is necessary to ensure the continued safety and reliability of the system. Replacement of the poles prior to significant deterioration to crossarms or the pole itself is of the utmost importance in regard to maintaining service and ensuring safety of the public. Therefore, the X178-2 rebuild is beneficial to public health and safety. The X178-2 Transmission Line was originally built in 1969 and additional portions were built in 1985. During an inspection of the X178 Transmission Line, it was observed that the structures are old and worn and have been subjected to pole splitting, woodpecker damage and rot, and must be replaced due to the state of deterioration of these structures over the past 55 and 39 years.

#5. For endangered species "Eversource will coordinate with the US Fish and Wildlife Service (USFWS) and USACE to determine if best management practices are required."


Eversource refuses to communicate with towns, the public, or easement-encumbered landowners who, if they even discover that there is an AoT submitted for their property, will have to submit a FOIA to USFWS, which doesn't do much protection since the Endangered Species Act, which was supposed to protect the habitat of endangered species, has been gutted by the money/power/influence of fossil fuel and fracking corporations as well as the ranching lobby.

"One need not take the world of the whistleblowers, as the statistical evidence in recent years, gleaned from the agency's own internat data, confirms Fish and Wildlife has been extraordinarily lax in enforcing the ESA. In a study published in the proceedings of the National Academy of Sciences, Ya-Wei Li examined the paperwork of 88,290 habitat consultations issued from January 2008 through April 2015. He was shocked at what he found. Only 7 percent involved a "formal" consultation, convened when FWS believes a project poses a serious threat to species. The other 93 percent garnered FWS approval without issue. Only two of the 88,290 consultations concluded there was jeopardy or adverse modification of habitat. "It boggles the mind to think the process is that smooth all the time," Li told me. "Tens of thousands of consultations, and only two jeopardy calls?" (And note that both of the two jeopardy decisions were later modified or reversed.)

The upshot is that during the seven-year period from 2008-2015 – the years of the Obama administration – not a single project was stopped or extensively altered as a result of FWS consultation. "When we published the report, I got a lot of calls from Fish and Wildlife people," Li told me. They were calling to thank him. "They told me I'd opened a can of worms at Fish and Wildlife." The consultation process, they said, was indeed "highly politicized." Biologists got punished for issuing jeopardy calls. The ESA's Republican detractors like to claim that the Fish and Wildlife Service is a hotbed of fanatical conservationists. If only it were so. The truth is that the leadership is weak, quiescent, compromised, and the underlings follow the leaders, as smart bureaucrats must do to stay employed. Attacked from without, the Endangered Species Act is also undermined from within." (This Land, by Christopher Ketcham, p. 221)

USFW is another captured agency.

#6.



The only protected species or habitat listed in this AoT application are High-Elevation Spruce-Fir Forest and Wood Turtles. What about the Northern Long-Eared Bat, Little Brown Bat, Common Nighthawk, Marten and Lynx?



ENDANGERED

Endangered wildlife are those native species that are in danger of extinction in New Hampshire because of a loss or change in habitat, over-exploitation, predation, competition, disease, disturbance or contamination. Assistance is needed to ensure these species' continued existence as viable members of the state's wildlife community.



INVERTEBRATES

Dwarf wedgemussel, Alasmidonta heterodon**
Brook floater mussel, Alasmidonta varicosa
Cobblestone tiger beetle, Cicindela marginipennis
Puritan tiger beetle, Cicindela puritana*
Frosted elfin butterfly, Callophrys irus
Karner blue butterfly, Lycaeides melissa samuelis**
White Mountain fritillary, Boloria titania montinus
Persius duskywing skipper, Erynnis persius
Rusty Patched Bumblebee, Bombus affinis**

FISH

American brook lamprey, Lethenteron appendix Shortnose sturgeon, Acipenser brevirostrum**

AMPHIBIANS

Marbled salamander, Ambystoma opacum

REPTILES

Blanding's turtle, *Emydoidea blandingii* Eastern box turtle, *Terrapene carolina*

Eastern hognose snake, Heterodon platirhinos Timber rattlesnake, Crotalus horridus

BIRDS

Northern harrier, Circus cyaneus Golden eagle, Aquila chrysaetos Common nighthawk, Chordeiles minor Piping plover, Charadrius melodus* Upland sandpiper, Bartramia longicauda Roseate tern, Sterna dougallii** Least tern, Sterna antillarum

MAMMALS

Eastern small-footed bat, Myotis leibii
Little brown bat, Myotis lucifugus
Northern long-eared bat, Myotis septentrionalis*
Tri-colored bat, Perimyotis subflavus
New England cottontail, Sylvilagus transitionalis
Canada lynx, Lynx canadensis*
Eastern wolf, Canis lupus**

"The USFWS is also required to designate "critical habitat" for a listed species when it is considered necessary or when critical habitat can be determined ¹³. Critical habitat identifies specific geographic areas and may include areas not currently occupied, but deemed necessary to conserve and recover a listed species ¹⁴. Federal agencies are not allowed to take any actions that would result in the destruction or adverse modification of critical habitat. "

https://extension.okstate.edu/fact-sheets/what-you-need-to-know-about-the-endangered-species-act.html

No critical habitat has been identified for the Northern Long-eared Bat or Monarch Butterfly.

Eversource is still required to determine how the proposed rebuild of the X-178, with noise, permanent roads and constructions pads, would affect endangered and threatened species and habitats.

Mammals

NAME

STATUS

Canada Lynx Lynx canadensis

Threatened

There is final critical habitat for this species. Your location does not overlap the critical habitat.

https://ecos.fws.gov/ecp/species/3652

Northern Long-eared Bat Myotis septentrionalis

Endangered

Wherever found

No critical habitat has been designated for this species. https://ecos.fws.gov/ecp/species/9045

Insects

NAME

STATUS

Monarch Butterfly Danaus plexippus

Candidate

Wherever found

No critical habitat has been designated for this species. https://ecos.fws.gov/eco/species/9743

Critical habitats


Potential effects to critical habitat(s) in this location must be analyzed along with the endangered species themselves.

There are no critical habitats at this location.

You are still required to determine if your project(s) may have effects on all above listed species.


Why are these pages shown as "Not for Consultation"?

#7. The AoT applications states that there is no critical lynx habitat around the X-178, yet the N.H. Canada Lynx Protection Zone for Trapping includes the area west of Route 116. Will the information above be in the AoT for the X-178-2 which covers the easement within White Mountain National Forest?



#8. Below: The X-178 in part of Sugar Hill, Easton, and part of North Woodstock. Orange indicates wildlife corridors and green indicates prioritized habitat. The corridors connect the habitat areas and continue through them. The X-178 has been degrading important wildlife corridors and habitat since 1948. It would not be permitted to be built now. The proposed rebuild, with 39 acres of permanent degradation of built roads and construction areas, and construction, with months of noise and pollution, will certainly drive many animals and humans out of a large area: Sound moves and reverberates for long distances in the Easton valley. The noise of a illegally mufflered motorcycle can travel more than a mile, so Eversource's proposed months of heavy construction will have extensive and and long term, if not permanent, effects on humans and wildlife. With audible construction noise comes infrasound, an additional physical and psychological stressor about which Eversource is also silent.

The red lines show a crude noise pollution zone for the X-178, with one mile travel for noise shown on either side of the line. The cleared easement would be a travel corridor for noise, so noise pollution within the cleared easement would be intense.



#9. And again, Eversource claims it owns the easements and DES ignores is own rules and accepts this claim:

"If the applicant is not the owner of the property, each property owner signature shall constitute certification by the signer that he or she is aware of the application being filed and does not object to the filing."

The applicant is not the owner of the property, and the vast majority of true owners are **unaware** that these applications have been filed and thus unable to object to the filing.

Eversource and DES have deliberately withheld information about major construction and terrain alteration from hundreds of easement-encumbered landowners.

| Initials: KN | If the applicant is not the owner of the property, each property owner signature shall constitute certification by the signer that he or she is aware of the application being filed and does not object to the filing. | | | |
|--|---|---|----------------------|--|
| SECTION 1 | 5 - REQUIRED SIGNATURES (Env-Wt 311 | .04(d); Env-Wt 311.11) | | |
| SIGNATURE | (OWNER): July | PRINT NAME LEGIBLY: Kurt Nelson | DATE: 2/21/2024 | |
| SIGNATURE (APPLICANT, IF DIFFERENT FROM OWNER): | | PRINT NAME LEGIBLY: | DATE: | |
| SIGNATURE (AGENT, IF APPLICABLE): Louising White | | PRINT NAME LEGIBLY: Lindsey White | DATE: 2/21/2024 | |
| SECTION : | 16 - TOWN / CITY CLERK SIGNATURE (En | v-Wt 311.04(f)) | | |
| As require | ed by RSA 482-A:3, I(a)(1), I hereby certify I four USGS location maps with the town, | that the applicant has filed four application /city indicated below. | forms, four detailed | |
| TOWN/CITY CLERK SIGNATURE: | | PRINT NAME LEGIBLY: | | |
| TOWN/CITY: | | DATE: | DATE: | |

Below, 2021 email from an easement-encumbered landowner to DES and DOJ:

| Sent: Sunday, November 21, 2021 11:04 AM | | | |
|---|---------------|--|--|
| To: Aslin, Christopher < Christopher.G.Aslin@doj.nh .> | | | |
| Cc: Michael McDonald < INV OF PRIVACY >; Anne | Norris | | |
| < INV OF PRIVACY | ; Trowbridge, | | |
| Philip < Philip < Philip | | | |

"As you are aware, property owners in New London have been investigating a number of permitting deficiencies associated with Eversource's rebuilding of the M 127 power corridor. These errors/omissions occurred with both state and municipal permits, and are traceable to process flaws within Eversource, within DES, and within the Town of New London. While we have painfully slogged through most issues, we have a couple of items left to resolve. Phillip Trowbridge gave us your name as the attorney who provided him with the legal opinion regarding who is the property owner of the land within Eversource's ROW as it pertains to DES AOT regulations.

The case law Phillip cited was from an adjudication completed in 2015, prior to DES significantly amending their AOT regulations, including defining key terms—Applicant, Agent, Owner, Person. Given the time line, the civil suit that surfaced the ambiguity with terms in the older Administrative Codes was a probable driver behind some of the changes that were adopted by Doc. #12342 effective 8-15-17. Additionally, in conjunction with the new rules/definitions, the AOT application form was significantly revised, hopefully tightening up points of confusion inherent in the older document.

The codified definition of "applicant" clarifies that an easement holder with a legal right to complete the work proposed in an AOT permit can submit an application, which in this specific case would be Eversource. The regulations also spell out what property owner information/signatures must be on the AOT permit and associated documentation submitted to Municipalities and to DES (ENV-WQ 1503.10). "Owner" in the amended Administrative Code (ENV-WQ 1502.45) is defined as the "Record Title Holder". Phillip has stated that based on your interpretation, Eversource is the singular "owner" of the underlying property. While we agree that Eversource has a title interest in this private property, and can apply for an AOT permit, we disagree that they are the exclusive "Record Title Holder" and can sign that application as the exclusive "owner". The regulations provide for multiple "owners" if applicable.

Interestingly, Eversource is quite clear that they do not own the underlying property but rather have a limited use easement on this private property. I am going to attach some policy information published by Eversource regarding their view on who owns the property/land that the pole structures and lines reside on, and how they define and distinguish the rights of the two entities. The easement on our property is quite specific relative to what Eversource can construct to maintain and operate this portion of the power grid. That easement does not limit our use of that land outside of state, federal, and industry-specific safety rules that are codified in statutes and

written policies. For example, we can plant and landscape the property within the easement boundaries. However, industry standards protecting the grid have specific rules relative to the maximum heights of trees within the power corridor, beginning with an 8-foot maximum directly under the power lines and ending with a 25-foot maximum at the outer perimeter of the easement boundary. Property owners cannot build a swimming pool within the easement boundary, but in New Hampshire, we can work with established snowmobile trail groups to allow those recreational activities to occur on our underlying property, even when it is within the easement boundary (although we have zero interest in snowmobile trails on our properties). Property owners with these easements attached to their land can and do include that underlying property within our Town Trail System. Some people grow crops within the easement. And we could go on with specific examples.

Property owners and the easement holder (now Eversource) both retain their title interests. We cannot interfere with Eversource's easement rights and Eversource cannot unreasonably restrict our enjoyment of private property. Eversource sums it up better than I can:

"The majority of the rights-of-way used for the Eversource electric transmission system were established through the purchase of easement rights by Eversource from owners of the underlying property. While we have rights to operate and maintain the electric transmission system through these easements, the underlying property is still owned by private parties. Their rights to use the property continue, subject to our easement rights."

I would add that Eversource is restricted by the specifics included in our easements and does not have a contractural right to "do whatever they want within the easement" which was apparently true in the cited case (Robert Michele). For example, our easement contracts state that Eversource can construct a "foundation suitable for the poles". That is something that can be quantified by a civil engineer familiar with the pole technology being utilized. Eversource cannot construct a permanent foundation on our properties that is 2,000 square feet if their pole engineer indicates they only need 500 square feet to safely and securely house the footings. That would be going outside what is specifically included in our easement contracts, and infringing on our rights as owners of that land.

Hopefully I have outlined our understanding of record title holder status relative to the easement. We believe that Eversource's publicly available documentation supports our interpretation. We understand that Eversource has a title interest in the land covered by the easement contracts along the M-127 power corridor. We disagree with DES/DOJ that Eversource is the exclusive owner/record title holder of the underlying land. Given that "Record Title Holder" is a term not defined in the

regulations, Merriam Webster apparently becomes the operative reference for clarifying what that term means. We have completed that analysis."

On Dec 9, 2021, at 1:50 PM, Aslin, Christopher < Christopher.G.Aslin@doj.nh. wrote:

"Thank you for reaching out in regard to NHDES's interpretation and application of its Alteration of Terrain (AOT) rules in relation to Eversource's transmission line maintenance on the M127 line through New London. NHDES's interpretation of its rules was reached in consultation with NHDOJ and was deemed a reasonable exercise of NHDES's administrative authority under RSA 485-A. I recognize that you have a different interpretation of the AoT rules and the meaning of "record title holder" and have already raised your concerns directly with NHDES staff. At this time there is no further role for NHDOJ in this matter.

Sincerely,

Chris Aslin

Christopher G. Aslin

Senior Assistant Attorney General

Environmental Protection Bureau

33 Capitol Street Concord, NH 03301 Phone (603) 271-3679

Fax (603) 271-2110"

Date: December 9, 2021 at 2:28:56 PM EST

To: Philip Trowbridge <philip.r.trowbridge@des.nh.>

Cc: Ridgely Mauck < Addison.R.Mauck@des.nh.gov>, christopher.aslin@doj.nh.gov

Subject: Re: Referral from Phillip Trowbridge


"This is quite circular. I asked that DES provide the legal basis for declaring Eversource the Record Title Holder as defined in the AOT regulations. You referred me to DOJ as the ones that provided you with that opinion. DOJ deflects back to DES' interpretation of its own rules, and indicates that you have the authority to make that legal interpretation.

So, my question to you is—what is the legal basis for your interpretation that Eversource is the singular Record Title Holder for AOT permitting purposes. If the answer is "Because I say So", then just tell me that and I will proceed accordingly."

The AG and DES need to confirm their "interpretations" of DES rules, and that they consider that this interpretation applies to all utility projects, including the X-178 and Eversource's 76+ other "Asset Condition" projects, and that "because I say so" is the extent of your justification for DES's failure to send easement-encumbered landowners the AoT applications or permits for extensive construction on their lands.

Are DES rules, like the terms of the easements, meaningless without a lawsuit?

#10. Another project description:



"The existing wood structures will be replaced with a new steel counterpart and will require heavy machinery to install." More untruths.

A counterpart is something closely resembling the original, having the same function and characteristics. The new structures would not closely resemble the existing structures, except perhaps from afar. They are metal, not wood, wider and taller, the conductor is larger, the distance from the cross-arms to the OPGW is greater, there are OPGW splice boxes on some of the structures, and signs warning of electrocution.

The metal structures do not have the same function as the existing wood structures, which is part of the reason they are taller and wider. The functions of the new structures are:

• To carry OPGW, which is not permitted in the terms of the easements and is heavier than the existing ground wires.

- To carry the three high-sag 1272 ACSS conductors, which combined, weigh 4,899 lbs per 1,000' compared to the three existing conductors which combined weigh 3,282 lbs per 1,000'.
- To place the OPGW approximately 15' from the conductors, which is where Eversource claims the height increases occur.
- To disempower easement-encumbered landowners by using structures they will be unable to remove without expensive metal cutting equipment, in the event of system destruction, decay, abandonment, or pole disposal in the easement, as was done in the 1985 replacement of the Beebe River to Streeter Pond Tap section of the X-178.
- For other reasons Eversource has not stated. Perhaps the metal structures are an excuse for the road building, depreciate in value in a way that benefits Eversource more than wood structure depreciation, are part of a deal with the corporations that make them, benefit Eversource because they do not required line-workers to climb them using spikes, so eliminate a skill-set in workers, cannot be repaired or replaced in ways that wood poles/structures can, or can be extended in height. The metal structures are lighter and do not required any equipment to install that differs from that used in 1985. Their installation does not require graded, permanent construction areas 100' x 100' (the cleared width of most of the existing easement where there is no distribution line) or permanent roads. Eversource's systematic and premature elimination of carbon-sequestering wood structures in favor of new carbon-intensive metal structures, remains unjustified and unexplained.

The Project Schedule and Sequence:

- "8. Conduct drilling activities, including drilling of approximately 4-ft. diameter holes for caisson placement, approximately 7-15' below ground surface. Dewater practices (e.g., dirt bags and temporary sediment basins in uplands) and proper stockpiling will be utilized during drilling. Drill spoils will be properly stabilized in non-jurisdictional areas."
- "10. Conduct structure replacement activities, including installation of new structures, and removal of old structures. Existing structures in wetlands are typically cut and pole butts left in place, while structures in uplands may be removed from the ground"

#12. Drill spoils may be contaminated with creosote, pentachlorophenol and other chemicals that have migrated from the existing poles, and should be disposed of in an appropriate landfill, not "non-jurisdictional areas" on the easements.

All wood pole butts must be removed, since they are heavily saturated with pentachlorophenol, creosote, fuel oil and other treatments for slowing decay.

Eversource has provided no documentation showing that removing these poles is more damaging to wetlands than leaving them to continue to contaminate wetlands.


Below: X-178 1985 poles with treatment cartridges: Methylisothiocyanate, chlorpyrifos or Tetrahydro-3,5-dimethyl-2H-1,3,5-thiadiazine-2-thione (Dazomet.)



Below: Older wood treatment cartridge in water:



X-178 1985 pole with two pole stubs and one 1948 dumped pole left in place to avoid wetland damage (according to Eversource.)



"Dazomet:GHS Hazard Statements

H302 (100%): Harmful if swallowed [Warning Acute toxicity, oral]

H315 (19.58%): Causes skin irritation [Warning Skin corrosion/irritation]

H319 (100%): Causes serious eye irritation [Warning Serious eye damage/eye irritation]

H400 (94.28%): Very toxic to aquatic life [Warning Hazardous to the aquatic environment, acute hazard]

H410 (100%): Very toxic to aquatic life with long lasting effects [Warning Hazardous to the aquatic environment, long-term hazard]"

https://pubchem.ncbi.nlm.nih.gov/compound/Dazomet#datasheet=LCSS

Below: X-178 pole still leaching chemicals into a Reel Brook watershed high-altitude bog, 2015



<u>5/10/62</u>: Pole treatment: "It is our understanding that the treatment consists of the application of a 6 percent solution of pentachlorophenol in number 2 fuel oil to the entire pole and cross arms and that the fire hazard created by this application continues for 24-36 hours...The area of high hazard is in the immediate vicinity of the pole where the oil drips into the ground."

(WMNF document)

Frog eggs in (vernal?) pool created by X-178 transmission pole installation, 2015:





Left: Wood-Fume pole treatment container discarded in 2019 near pole 246, Bog Pond area (photo 2023.)

Wood-Fume ENVIRONMENTAL HAZARDS

"This pesticide is toxic to mammals, birds, fish, and aquatic vertebrates."

"CONTAINER HANDLING: (container 5 gallons or less)

Nonrefillable container. Do not reuse or refill this container. Triple rinse as follows: Fill container ¼ full with water and recap. Shake for 10 seconds. Follow Pesticide Disposal instruction for rinsate disposal. Drain for 10 seconds after flow begins to drip. Repeat procedures two more times. Then offer for recycling if available or recondition if appropriate or puncture and dispose of in a sanitary landfill, or by other procedure approved by state and local authorities."

Do Lentrek, Super Fume and Wood-Fume contain PFAS?

Super-Fume and Wood-Fume treatment tags on X-178 pole 246:



Five gallon Timberline Wood Treatment container dumped near structure 324. Beech Hill, Mt. Blue, Moosilauke and Mt. Clough in the background.





PRODUCT: TIMBERLINE WOOD PRESERVING COMPOUND

• **REGISTRATION NUMBER:** 3008-4-ZA

• **COMPANY NAME:** KOPPERS PERFORMANCE CHEMICALS, INC.

• PRODUCT STATUS: C - INACTIVE NOT RENEWED

REGISTRATION

REGISTRATION DATE: 22-SEP-87
INACTIVATION DATE: 31-DEC-91

Chemical Information

| Code | Name | Percent |
|-------|----------------------|------------|
| 0 | INERT INGREDIENTS | 4.86000 |
| 171 | CREOSOTE | 45.62000 |
| 537 | SODIUM FLUORIDE | 44.42000 |
| 2167 | POTASSIUM DICHROMATE | 3.10000 |
| 221 | 2,4-DINITROPHENOL | 2.00000 |
| Total | | 100.00000% |

https://apps.cdpr.ca.gov/cgi-bin/label/labrep.pl?fmt=1&8502=on

Timberline contains "2,4-Dinitrophenol (DNP): A Weight Loss Agent with Significant Acute Toxicity and Risk of Death"

https://www.ncbi.nlm.nih.gov/pmc/articles/PMC3550200/

"<u>Potassium Dichromate</u> is a CARCINOGEN in humans. There may be no safe level of exposure to a carcinogen, so all contact should be reduced to the lowest possible level. The above exposure limits are for air levels only. When skin contact also occurs, you may be overexposed, even though air levels are less than the limits listed above."

https://nj.gov/health/eoh/rtkweb/documents/fs/1564.pdf

"Creosote may pose risks to fish and invertebrates when creosote-treated wood is used in aquatic and railroad structures."

https://www.epa.gov/ingredients-used-pesticide-products/creosote

#13. The AoT application shows Stephen Whitcomb as owner of WMNF, and two different lines (green hatched and white) for the boundaries of the White Mountain National Forest, as do the other project maps.

#14. Birds of Conservation Concern; Canada Warblers, Chimney Swifts, Kestrels, Olive-sided Flycatchers, Common Kestrels, Veery and Wood Thrushes, Ruffed Grouse, Purple Finches and Northern Goshawks are all in the project area. There is no protection for them in the project plans.

| Bicknell's Thrush Catharus bicknelli | Breeds Jun 10 to Aug 2 |
|---|-------------------------|
| This is a Bird of Conservation Concern (BCC) throughout its | |
| range in the continental USA and Alaska. | |
| https://ecos.fws.gov/ecp/species/606 | |
| Black-billed Cuckoo Coccyzus erythropthalmus | Breeds May 15 to Oct 1 |
| This is a Bird of Conservation Concern (BCC) throughout its | |
| range in the continental USA and Alaska. | |
| https://ecos.fws.gov/ecp/species/9399 | |
| Bobolink Dolichonyx oryzivorus | Proods May 20 to Jul 21 |
| This is a Bird of Conservation Concern (BCC) throughout its | Breeds May 20 to Jul 31 |
| range in the continental USA and Alaska. | - |
| Canada Warbler Cardellina canadensis | 210 |
| This is a Bird of Conservation Concern (BCC) throughout its | Breeds May 20 to Aug 10 |
| range in the continental USA and Alaska. | · KA' |
| Cape May Warbler Setophaga tigrina | 1/1. |
| This is a Bird of Conservation Concern (BCC) only in particular | Breeds Jun 1 to Jul 31 |
| Bird Conservation Regions (BCRs) in the continental USA | |
| Chimney Swift Chaetura pelagica | Droods May 45 |
| This is a Bird of Conservation Concern (BCC) throughout its | Breeds Mar 15 to Aug 25 |
| range in the continental USA and Alaska. | |
| Evening Grosbeak Coccothraustes vespertinus | Breeds May 15 to Aug 10 |
| This is a Bird of Conservation Concern (BCC) throughout its | Dreeds May 13 to Aug 10 |
| range in the continental USA and Alaska. | |
| Olive-sided Flycatcher Contopus cooperi | Breeds May 20 to Aug 31 |
| This is a Bird of Conservation Concern (BCC) throughout its | 20 to Aug 31 |
| range in the continental USA and Alaska. | |
| https://ecos.fws.gov/ecp/species/3914 | |
| Wood Thrush Hylocichla mustelina | Breeds May 10 to Aug 31 |
| This is a Bird of Conservation Concern (BCC) throughout its | |
| range in the continental USA and Alaska. | |


To see a bar's survey effort range, simply hover your mouse cursor over the bar.


No Data (-)

A week is marked as having no data if there were no survey events for that week.

Survey Timeframe

Surveys from only the last 10 years are used in order to ensure delivery of currently relevant information. The exception to this is areas off the Atlantic coast, where bird returns are based on all years of available data, since data in these areas is currently much more sparse.





The X-178 is the light grey straight line in the middle-right that goes through the green "suitable foraging" area and two pink hatched "suitable denning" areas for Lynx.



kris pastoriza

june 7, 2024

Redaction Date: 8/5/2024 1:14:42 PM

Redaction Log

Total Number of Redactions in Document: 4

Redaction Reasons by Page

| Page | Reason | Description | Occurrences |
|------|----------------|--|-------------|
| 1 | INV OF PRIVACY | NH RSA 91-A:5 IV Confidential information which would constitute an invasion of privacy if disclosed | 1 |
| 27 | INV OF PRIVACY | NH RSA 91-A:5 IV Confidential information which would constitute an invasion of privacy if disclosed | 1 |
| 37 | INV OF PRIVACY | NH RSA 91-A:5 IV Confidential information which would constitute an invasion of privacy if disclosed | 2 |

Redaction Date: 8/5/2024 1:14:42 PM

Redaction Log

Redaction Reasons by Exemption

| Reason | Description | Pages (Count) |
|----------------|--|------------------------|
| INV OF PRIVACY | NH RSA 91-A:5 IV Confidential information which would constitute an invasion of privacy if disclosed | 1(1) 27(1) 37(2) |