# B112 Transmission Line Rebuild Project White Mountain National Forest Sandwich, New Hampshire



Photograph No. 1: Looking at proposed access and work pad location adjacent to Structure 66.



Photograph No. 2: Looking at proposed access and work pad location for Structure 70.

### B112 Transmission Line Rebuild Project White Mountain National Forest Sandwich, New Hampshire



Photograph No. 3: Looking at proposed access and work pad location for Structure 77.



Photograph No. 4: Looking at proposed access and work pad location for Structure 81.

## B112 Transmission Line Rebuild Project White Mountain National Forest Sandwich, New Hampshire



Photograph No. 5: Looking at proposed access and work pad location for Structure 87.



Photograph No. 6: Looking at proposed access and work pad location for Structure 95.

# B112 Transmission Line Rebuild Project White Mountain National Forest Sandwich, New Hampshire



Photograph No. 7: Looking at proposed access and work pad location for Structure 97.



Photograph No. 8: Looking at proposed access and work pad location for Structure 100.

## B112 Transmission Line Rebuild Project White Mountain National Forest Sandwich, New Hampshire



Photograph No. 9: Looking at proposed access and work pad location adjacent to Structure 108.



Photograph No. 10: Looking at bear damage to Structure 110.

# B112 Transmission Line Rebuild Project White Mountain National Forest Sandwich, New Hampshire



Photograph No. 11: Looking at proposed access and work pad location for Structure 116.



Photograph No. 12: Looking at proposed access and work pad location for Structure 118.

# B112 Transmission Line Rebuild Project White Mountain National Forest Sandwich, New Hampshire



Photograph No. 13: Looking at proposed access and work pad location for Structure 121.