

STATE OF NEW HAMPSHIRE  
DEPARTMENT OF RESOURCES AND ECONOMIC DEVELOPMENT

LAND AND WATER CONSERVATION FUND PROGRAM

IN-PROGRESS ON-SITE INSPECTION REPORT

State: New Hampshire Project Number: 33-00691 Inspection Date: 1/6/16  
 Project Period: \_\_\_\_\_ ends 12/31/16 Type of Project: Development

Project Name and Sponsor: Jericho DNED  
 Inspected by: Johanna Lyons Accompanied by: Tom Mansfield  
 Agency: DNED Agency: DNED

Prior Inspections: none

1. Is the project being carried out in accord with the project proposal?
2. Can the remaining work be completed during the project period?
3. Are provisions being made for use of the facilities by the handicapped?
4. Are health/safety measures adequate to protect workers and visitors?
5. Are construction plans, materials, and workmanship satisfactory?
6. Are natural features and other park facilities adequately protected?

Yes	No
✓	
✓	
✓	
✓	
✓	
✓	

Comments and Description of Work Done

Framing of the new bathhouse is 65% complete.

Notes to Future Inspectors

Photographs attached? Yes  X  No

Reviewed by: [Signature] Inspector: Johanna Lyons

Title: Program Specialist Title: Planning + Devel. Specialist



Exterior East View



Exterior West View



Interior East View, Toilet Rooms & Store



Interior West View, Shower Rooms

Pictures taken 1/6/16 by Johanna Lyons