



Representative Photographs



Photo 1: View north toward the WMNF boundary and Structure 160.



Photo 2: View southeast of Structure 160 from within the WMNF.



Photo 3: View northwest of Structure 161; Structures 162, 163 and 164 also visible.



Photo 4: Closeup of Structure 161 with woodpecker and insect damage.



Photo 5: View northwest toward Structure 162; Structures 163, 164 and 165 visible in distance.



Photo 6: View southeast toward Structure 162 from Structure 163.



Photo 7: Closeup view of Structure 163.



Photo 8: View southeast of Structure 163.



Photo 9: View northwest of Structure 164.



Photo 10: View northwest of Structure 164 (foreground), and Structure 165 (middle ground) near the WMNF boundary.